Oil Field Environmental Incident Summary

Incident: 20170609233210   **Date/Time of Notice:** 06/09/2017   23:32

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: TRMU 12-12H

Field Name: T. R.   **Well File #:** 16029

Date Incident: 6/9/2017   **Time Incident:** 01:52   **Facility ID Number:**

County: BILLINGS   **Twp:** 141   **Rng:** 101   **Sec:** 12   **Qtr:**   NW SW

Location Description:

Submitted By: Rebecca Sample   **Received By:**

Contact Person: Rebecca Sample
                      4901 LBJ FREEWAY, STE 300
                      DALLAS, TX 75244

General Land Use: Well/Facility Site   **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 2 Mile
Distance Nearest Water Well: 2 Mile

Type of Incident: Pump Leak

Release Contained in Dike: No   **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	22	Barrels	22	Barrels	22	barrels
Brine						
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 9/15/2017   **Clean Up Concluded:** 8/17/2017

Risk Evaluation:
None

Areal Extent:
Approximately a 20' x 6' patch of grass has a fine spray mist of oil.

Potential Environmental Impacts:
None

Action Taken or Planned:

A vac truck was sent to clean up the oil spill and put oil back into oil storage tank. A steam truck cleaned up the mess and the vac truck also cleaned up that oily water. We will wait for advice from state as to what you would like us to do with the mist on the grass

Wastes Disposal Location: Either R360 or Indian Hills Disposal

Agencies Involved:

Updates

Date: 6/12/2017   **Status:** Reviewed - Follow-up Required   **Author:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:
Release, due to a pump leak, was not contained, according to the report. Further follow-up needed.

Date: 6/29/2017   **Status:** Inspection   **Author:** Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:
6/26/2017 at 19:09, on location. Pump building located along northwestern edge of pad, and visibly impacted vegetation including grasses and shrubs visible to the west.